Western Electric Co., Incorporated, Engineering Dept.,
New York.

(2 Pages) Page #1. Issue 2 - BT-431304. April 21, 1920.

METHOD OF OPERATION RINGING CIRCUIT

For Secondary Testing Cord Circuit - Local Test Desk - Full Mechanical Power Driven System.

GENERAL DESCRIPTION

1. These circuits are used in a local test desk at a mechanical office, in connection with primary and secondary testing cords to provide means for semi-selective ringing of the stations on a two or four party line.

DETAILED DESCRIPTION

OPERATION

FIGURE #1. TWO OR FOUR PARTY SEMI-SELECTIVE RINGING

- 2. When the subscriber's line under test is selected by means of a sender, the PMG or SMG relay in the testing cord circuit operates, furnishing ground to the lead C. When the R or M key is operated, the R relay operates over a circuit from battery through its winding, break contacts of the T-1 and T-2 relays, break contact of the RR relay, make contact of the R or M key to ground on lead C. The R relay operated, furnishes battery to the 1200 ohm winding of the PU relay which operates under control of the pick-up interrupter and locks through its make contact, connecting "2 RING" machine ringing current to the ring or tip of the line according to the key operated. The PU relay is used in the circuit to apply ringing current at the start of the "2 RING" code thereby preventing a false code. When the receiver is removed from the switchhook at the called station, the T-2 relay operates removing the short circuit from the winding of the RR relay which operates in series with the R relay. The RR relay operated functions as follows: - (a) Disconnects ringing current from the tip and ring leads T-1 and R-1. (b) Lights the TR lamp. (c) Opens a contact to prevent its being short circuited upon the release of the T-2 relay. (d) Connects ground to the tip side of the subscriber's line and the supervisory relay on the ringside of the secondary testing cord circuit to the ring of the subscriber's line for supervisory purposes. When the test man restores the ringing key, the R and RR relays release, restoring the circuit to normal.
- 3. When the W or J party key is operated, the circuit functions as above described with the exception that the "1 RING" test machine ringing current is applied by the key to the ring or tip of the line through the T-1 relay directly and independently of the PU relay.

FIGURE #2. TWO PARTY SELECTIVE RINGING

4. The operation of the AICT key to call either of the two stations performs the same functions as above described for the operation of the "W" or "J" keys. The only exception is that the R relay of Figure #1 is here replaced by a #18-G resistance.

(2 Pages) Page #2. Issue 2 - BT-431304. April 21, 1920.

CIRCUIT REQUIREMENTS

			CIRCUIT REQUIREMENTS	The Times about
		OPERATE	NON-OPERATE	RELEASE
	114-AK (T) (T-1) and (T-2)	With ringing machine at approximately 1200 R.P.M. Test .033 amp. Readj032 amp. With ringing machine at approximately 1000 R.P.M. Test .037 amp. Readj036 amp.	With ringing ma- chine at approx- imately 1200 R.P.M. Test .029 amp. Readj030 amp. With ringing ma- chine at approx- imately 1000 R.P.M. Test .033 amp. Readj034 amp.	
	E75	Test .035 amp. Readj011 amp.	cers " or approved	Test .0026 amp. Readj0028 amp.
•	E212 (RR)	Test .045 amp. Readj040 amp.	Test .028 amp. Readj030 amp.	
	Sp1. E per D-12829	Test .011 amp. Readj010 amp.		Test 0023 amp. Readj. 0025 amp.
	Inner Wdg.		CIRCUIT REQUIREMENTS	The Control of the Co
		CPERATH	NON-OPERATE	REIEASE
	114-97 (T) (7-1) and (T-2)	With ringing ma- chine at approx- imately 1200 R.P.H. Tost .033 ang. Readjr .032 amp.	With ringing was chine at approx. Imstely 1200 R.P.M. Pess .029 amp. Roadj030 amp.	
		With ringing ma- enine at approx- imately 1000 R.P.M. Hers .037 amp. Roudj036 amp.	With ringing ma-	
	E75	Test .035 cmp. Roadj: .053 cmp.		Test .0026 emp. Readj0028 emp.
	E212	Toot .043 amp.	Pest .028 map.	

ENG. -- WES- JO. CHK'D. -- CHW. CAC APPROVED - C. L. SLUYTER, G.M. L.